IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicants: John Piechowiak et al.) CONFIRMATION NO. 2684
Appln. No.: 10/730,742 Filed: December 8, 2003 Title: METHOD, SYSTEM AND APPARATUS FOR OPENING DOORS	This Request For Certificate Of Correction Of Patent For PTO Mistake was electronically filed on February 20, 2007 using the U.S. Patent and Trademark Office's EFS Web
Patent No.: 7,151,351 B2))
Issued: December 19, 2006)
Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450	

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE

ATTENTION: Certificate of Correction Branch
Office of Patent Publication

Sir:

file are:

In accordance with 37 C.F.R. § 1.322(a), the above-specified patentees, through their attorneys, respectfully request that a Certificate of Correction be issued for the above-referenced patent to correct the following errors.

The exact page and line number where the errors occurred in the application

Please insert the following paragraphs before "Programming Car Remote" Column 8. Line 23

 LOW BATTERY: A low battery symbol illuminates when car remote's battery is low. Change Car Remote battery as soon as possible.

SAFETY FAULT: A safety fault symbol illuminates when photo eye sensors have been tripped or there is a door jam.

LOCK: Illuminates when the system vacation lock is engaged. --

REMARKS

The above-requested changes result from errors which occurred during printing of the patent on the part of the Patent Office. Attached hereto is Form PTO/SB/44 incorporating the requested changes.

It is believed that issuance of a Certificate of Correction is appropriate without expense to the Patentee, and issuance of such Certificate is respectfully requested.

Please send the Certificate to:

Kenneth H. Samples, Esq. FITCH, EVEN, TABIN & FLANNERY 120 South LaSalle Street, Suite 1600 Chicago, Illinois 60603-3406

Respectfully submitted,

FITCH, EVEN, TABIN & FLANNERY

Date: 2//9/07

Kenneth H. Samples
Registration No. 25.747

120 South LaSalle Street, Suite 1600 Chicago, Illinois 60603

312/577-7000

alid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _1_ of _1_

PATENT NO. : 7,151,351 B2 APPLICATION NO. : 10/730,742

ISSUE DATE : December 19, 2006 INVENTOR(S) : John Piechowiak et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Please insert the following paragraphs before "Programming Car Remote" Column 8, Line 23

-- LOW BATTERY: A low battery symbol illuminates when car remote's battery is low. Change Car Remote battery as soon as possible.

SAFETY FAULT: A safety fault symbol illuminates when photo eye sensors have been tripped or there is a door jam.

LOCK: Illuminates when the system vacation lock is engaged. --

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Fitch, Even, Tabin & Flannery 120 South LaSalle Street, Suite 1600 Chicago, Illinois 60603-3406